



View West - Pooling diesel fuel east of the canopy.



View Northwest - Additional pooling southeast of the Radio Shop.



View North - Between the tracks and the Radio Shop.



View Northwest - Vacuuming pooled diesel fuel. Radio Shop is displayed in the background.



View Southwest - Vacuuming and applying absorbent to the spill area.



View Northwest - Impacted area after applying absorbent.



View South - Service Trench collected some of the released diesel on the north end of Service Track 1.



View Southwest - Dispenser 10, tagged out of service.



View Northwest - Impacted area on October 6, 2005.



View West - Impacted area on October 6, 2005.



View of site upon completion of activities.